


09/182842

BEHL1318

1/3

attch
to #9
Drift #



Approved
except
as noted
22

FIG.-1
(PRIOR ART)

12-00

44

34

plug not the locking assembly

52

64-Fig 3

PC card device

BEHL1318

2/3




FIG.-2

offset slots

handle

new matter

09/18842-24881/60

BEHL1318

3/3




FIG.-3

Under
if 48 is in
carrier 32 in
fig 3, why is
it on part 62
in fig 4




FIG.-4